

Fig. 1





Fig. 2

POLISHING RATE ($\text{\AA}/\text{min}$)



2/
6

Fig. 3

POLISHING RATE ($\text{\AA}/\text{min}$)





Fig. 4



3/
6

Fig. 5




Fig. 6

NUMBER OF
SUBSTRANCES




Fig. 7A




Fig. 7B




Fig. 7C




Fig. 7D




Fig. 7E




Fig. 8

